School:	Borough Road Nursery						
AMP Category	Work/Project	Justification	Budget		Primary 4		
External Walls Windows And Doors	Window Replacement - Phase 2	Required to prevent possible water ingress, address potential H&S risk	£15,000	D E15,000	Hod €0		
Suitability Projects	Formation of hygiene	and improve energy efficiency Required to provide DDA compliant	£5,000	£0	£0		
Suitability Projects	room Suitability Projects Adaptations for Resource Room	facilities for identified pupil need School require additional teaching space	£11,000	£0	£0		
	110000000000000000000000000000000000000	Totals	£31,000	£15,000	£0		
DECAME C C	4.35						

DFC Allocation & Adjustment

DFC allocation for 06/07 £19,593
Plus/minus C/F £0
Amount available £19,593

Under/over spend £4,593 (NB. Carry forward to support anticipated 07/08 projects)

AMP Category	Work/Project	Justification	Budget		Primary	I
Electrical	Fire Alarm and Emergency Lighting	The school currently has an outdated manual alarm system. This does not meet current fire safety standards	£25,000	29 625,000	TO Mod - Prin	Mand
		Totals	£25,000	£25,000	£0	

DFC Allocation & Adjustment

 DFC allocation for 06/07
 £27,553

 Plus/minus C/F
 £2,414

 Amount available
 £29,967

Under/over spend £4,967 (NB. Carry forward to support anticipated 07/08 projects)

School:	Abbey Infant				
AMP Category	Work/Project	Justification	Budget		Primary a4
External Walls Windows And Doors Mechanical Works	Window Replacement - Phase I Heating renewal	Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and improve energy efficiency Existing underfloor heating system failing, work required to ensure fully	£40,000 £150,000	£20,000 £10,000	£20,000
		operational heating system and improve energy efficiency Totals	£190,000	£30,000	£160,000

DFC Allocation & Adjustment

DFC allocation for 06/07 £33,531
Plus/minus C/F £0
Amount available £33,531

Amount available
Under/over spend £3,531 (NB. Carry forward to support anticipated 07/08 projects)

School:	Dodmire Infants School						
AMP Category	Work/Project	Justification	Budget		rimary		
				DFC	Mod - Primary		
Suitability	Main Entrance Access Ramp and Handrails	The existing entrance does not meet the required DDA standards. Works would make the school fully	£6,000	£3,000	£0		
Security	Installation of CCTV system	The school has suffered significant vandalism damage and theft over the past two years. This joint project with the junior school and Children's Centre is designed to provide Town Hall monitored coverage for the whole site	£45,000	£19,500	£0		
		Totals	£51,000	£22,500	£0		

The property of the second

DFC Allocation & Adjustment

 DFC allocation for 06/07
 £31,274

 Plus/minus C/F
 £1,800

 Amount available
 £33,074

Under/over spend £10,574 (NB. Carry forward to support anticipated 07/08 projects)

School:	Mowden Infants				
AMP Category	Work/Project	Justification	Budget		Mod - Primary
				DFC	Mod -
Electrical	Rewire	The existing electrical system is outdated and poses a health and safety risk due to the condition of its wiring. In the previous financial year the school had its fire alarm and emergency lighting replaced as a	£110,000	£12,500	£97,500
External Walls Windows And Doors	Window Replacement - Phase 1	phase 1 of the overall scheme. Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and	£20,000	£20,000	£0
Suitability	Accessibility Works to Main Entrance	improve energy efficiency The existing entrance does not meet the required DDA standards. Works would make the school fully	£10,000	£0	£0
		Totals	£140,000	£32,500	£97,500

DFC Allocation & Adjustment

 DFC allocation for 06/07
 £28,590

 Plus/minus C/F
 £9,937

 Amount available
 £38,527

Under/over spend £6,027 (NB. Carry forward to support anticipated 07/08 projects)

School:	Abbey Junior					
AMP Category	Work/Project	Justification	Budget		Primary	ì
External Walls Windows And Doors	Window Replacement - Phase 1	Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and improve energy efficiency	£40,000	£20,000	£20,000	
		Total	ds £40,000	£20,000	£20,000	

DFC Allocation & Adjustment

DFC allocation for 06/07

£39,265

Plus/minus C/F

£0

Amount available Under/over spend

£39,265

£19,265 (NB. Carry forward to support anticipated 07/08 projects)

School:	Dodmire Junior				
AMP Category	Work/Project	Justification	Budget		Mod - Primary A
				DFC	
Security	Installation of CCTV system	The school has suffered significant vandalism damage and theft over the past two years. This joint project with the junior school and Children's Centre is designed to provide Town Hall monitored coverage for the	£45,000	£19,500	03
Suitability	Formation of access doorway and ramp to rear of school	whole site The recent development of a Multi Use Games Area to the school has led to the requirement for a dsignated access point from the rear of the building	£7,000	£7,000	£0
		Totals	£52,000	£26,500	£0

DFC Allocation & Adjustment

DFC allocation for 06/07

£35,849

Plus/minus C/F

-£8,595

Amount available

£27,254

Under/over spend

£754 (NB. Carry forward to support anticipated 07/08 projects)

School:	Mowden Junior						
AMP Category	Work/Project	Justification	٠	Budget		Primary	Fu
External Walls Windows And Doors	Window Replacement - Final Phase	Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and improve energy efficiency	•	£53,000	£53,000	£0	
		, 5,	Totals	£53,000	£53,000	£0	

DFC Allocation & Adjustment

 DFC allocation for 06/07
 £32,738

 Plus/minus C/F
 £3,013

 Amount available
 £35,751

Under/over spend -£17,249 (NB: To be drawn down from 07/08 Allocation)

School:	ool: Bishopton/Redmarshall Primary						
AMP Category	Work/Project	Justification	Budget		Primary	Fu	
				DFC	Mod - Pri		
Int Walls & Doors	New internal doors	Upgrade door to internal corridors to meet DDA & fire regs requirements	£7,500	£7,500	£0		
Suitability Projects	Alter shared staff room and reception	Required to enlarge staff room to provide lesson preparation area.	£5,000	£5,000	£0		
		Totals	£12,500	£12,500	£0		

DFC Allocation & Adjustment

DFC allocation for 06/07

£21,758

Plus/minus C/F

-£4,987 (NB. Commitment for Ph3 of Window Replacement Project)

The state of the s

Amount available

£16,771

Under/over spend

£4,271 (NB. Carry forward to support anticipated 07/08 projects)

School:	Corporation Road Primary							
AMP Category	Work/Project	Justification	Budget		Primary	Fu		
Suitability	Remodeling Works	Essential remodelling works to redress condition needs, improve teaching environment and provide grassed playing area within confines of the site. NB: Proposed budget for the project is £450,000 with works phased over 2 financial years	£204,744	2 4 £71,244	- DOM £0			
		Totals	£204,744	£71,244	£0			

DFC Allocation & Adjustment

DFC allocation for 06/07

£36,947

Plus/minus C/F

£0

Amount available

£36,947

Under/over spend

-£34,297 (NB: To be drawn down from 07/08 Allocation)

School:	Firthmoor Primar	y				
AMP Category	Work/Project	Justification	Budget		Primary	Fu
Security	Window Security Shutters	The school has suffered extensive vandalism damage and theft in the past year. Shutters have been identified as the most effective preventative measure for the school	£53,000	£53,000	- Po Wod -	
		Totals	£53,000	£53,000	£0	

e transfer and the second second

DFC Allocation & Adjustment

DFC allocation for 06/07

£31,915

Plus/minus C/F

£0

Amount available

£31,915 -£21,085 (NB: To be drawn down from 07/08 Allocation)

Under/over spend

School:	Gurney Pease Prima	nry			
AMP Category	Work/Project	Justification	Budget		Primary _e s
Electrical	Fire Alarm and	The school currently has an outdated	£25,000	ပ္ £25,000	B Mod - Primary
Suitability	Emergency Lighting Toilet Refurbishment ~ Girls and Boys	manual alarm system, that does not meet current fire safety standards The existing toilets old and outdated. Health & Safety issues arrise due to the deteriorated surfaces and poor	£15,000	£15,000	£0
Suitability	Formation of Storage Area to Hall	condition of the fixtures The School currently lacks a storage facility for the Hall	£7,872	£7,872	£0
Suitability		The location of the school near to a busy road leads to noise pollution to certain classrooms. Sound prrofing is a necessity to improve learning	£5,000	£5,000	£0
Suitability	Construction of Nursery	environment	£103,586	£0	£0
		Totals	£131,458	£27,872	£0

DFC Allocation & Adjustment

DFC allocation for 06/07 £27,614
Plus/minus C/F £2,103

Plus/minus C/F
Amount available £25,511

Under/over spend -£2,361 (NB: To be drawn down from 07/08 Allocation)

School:	Heathfield Primary				
AMP Category	Work/Project	Justification	Budget		- Primary M
External Walls Windows And Doors	Window Replacement - Phase 3	Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and improve energy efficiency	£70,000	£20,000	£50,000
Suitability	Toilet Block Refurbishment ~ Phase	The existing toilets old and outdated. 2 Health & Safety issues arrise due to the deteriorated surfaces and poor condition of the fixtures	£20,000	£20,000	£0
		Totals	£90,000	£40,000	£50,000

The state of the s

DFC Allocation & Adjustment

 DFC allocation for 06/07
 £45,274

 Plus/minus C/F
 £3,388

 Amount available
 £48,662

Under/over spend £8,662 (NB. Carry forward to support anticipated 07/08 projects)

School:

Heighington Primary

AMP Category	Work/Project	Justification	Budget		imary	F
Suitability	Toilet Block Extension and Remodel of existing toilet area	The toilets in the school are old and outdated, the school also lacks a DDA compliant Hygiene room. The existing cloaks facilities at the school are undersized and are also deemed a fire risk by the Fire Authority. Due to the significant investment in the school building over the past 6 years such suitability projects are now able to be programmed	£110,900	₽ £75,000	⊕ Mod - Primary	
		Totals	£110,000	£75,000	£0	_

DFC Allocation & Adjustment

£32,311 DFC allocation for 06/07 £43,776 Plus/minus C/F

£76,087 Amount available

£1,087 (NB. Carry forward to support anticipated 07/08 projects) Under/over spend

School:	High Coniscliffe Primary						
AMP Category	Work/Project	Justification	Budget		Primary	Fu	
Suitability	Extension to form a resource facility	The school currently lacks any designated area for staff preparation, meetings or ICT. Due to significant investment in the building in the past 6 years the school is now at a standard where such Suitability improvements can be programmed.	£135,000	000,023 DEC	- pow £0		
		Totals	£135,000	£50,000	£0		

DFC Allocation & Adjustment

DFC allocation for 06/07

£23,588

Plus/minus C/F

£35,934

Amount available

£59,522

Under/over spend

£9,522 (NB. Carry forward to support anticipated 07/08 projects)

School:	Hurworth Primar	у						
AMP Category	Work/Project	Justification	Budget		Primary	Fu		
Suitability	Toilet Extension	The existing toilet block is outdated and unsuitable for continued use.	£84,000	£60,000	£24,000			
		Totals	£84,000	£60,000	£24,000			

DFC Allocation & Adjustment

DFC allocation for 06/07

£30,786

Plus/minus C/F

£20,852

Amount available

£51,638

Under/over spend

-£8,362 (NB: To be drawn down from 07/08 Allocation)

School:	Mount Pleasant Pri	mary			
AMP Category	Work/Project	Justification	Budget		rimary A
				DEC	3 Mod - Primary
External Walls Windows And Doors	Window Replacement - Phase 1	Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and improve energy efficiency	£55,000	£55,000	£0
Suitability Issue	Playground Resurface	The existing surface is badly deteriorated and now poses health and safety hazards to the pupils	£15,000	£15,000	£0
Mechanical	Repairs to Pipework	Contingency for essential repairs for hot and cold water pipework to satisfy health and safety requirements	£10,000	£0	£10,000
		Totals	£80,000	£70,000	£10,000

DFC Allocation & Adjustment

 DFC allocation for 06/07
 £34,568

 Plus/minus C/F
 £36,858

 Amount available
 £71,426

Under/over spend £1,426 (NB. Carry forward to support anticipated 07/08 projects)

School:	North Road Primar	y									
AMP Category	Work/Project	Justification	Budget		Mod - Primary	Fu					
				DFC	- poW						
Suitability	Kitchen Upgrade	The existing kitchen facilities are deemed unsuitable for the schools requirements	£20,000	£20,000	£0						
Suitability	External Corrdors	Feasibility/design works for proposed corridor formation in 2007-2008	£10,000	£0	£10,000						
Suitability	Toilet Refurbishments	The existing toilets old and outdated. Health & Safety issues arrise due to the deteriorated surfaces and poor condition of the fixtures	£3,000	£3,000	£0						
Suitability	Resurface of Nursery Playground	The existing surface is badly deteriorated and now poses health and safety hazards to the pupils	£5,000	£5,000	£0						
		Totals	£38,000	£28,000	£10,000						

DFC Allocation & Adjustment

£41,095 DFC allocation for 06/07 Plus/minus C/F

Amount available

Linder/over spend

£2,326

£43,421

£15,421 (NB. Carry forward to support anticipated 07/08 projects)

School:	Redhall Primary					
AMP Category	Work/Project	Justification	Budget		Primary	Fu
External Walls Windows And Doors	Window Replacement - Phase 1	Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and	£60,000	£20,000	£40,000	
		improve energy efficiency	£0	£0	£0	
		Tot	tals £60,000	£20,000	£40,000	

DFC Allocation & Adjustment

DFC allocation for 06/07

£31,030

Plus/minus C/F

£14,396

Amount available

£45,426

Under/over spend

£25,426 (NB: Comitment towards proposed 07/08 Electrical Rewire project)

School:	Reid Street Primary	y .				
AMP Category	Work/Project	Justification	Budget		Mod - Primary	
Suitability	Formation of new entrance and Admin Block	The existing school layout is the same as it was since it was built in the late 19th Century. The current accomodation is wholly unsuitable for teaching practices in the 21st	£105,000	₽ G £75,000	FO Wod-	Mod -
Suitability	Adaptaion of existing Dining Facility	century and as such a full remodel of the school is being investigated. The Main entrance and circulation areas are poor The existing Dining Facility is undersized and is unsuitable for the number of pupils on roll at the school. This leads to significant supervision issues	£40,000	£30,000	£0	
		Totals	£145,000	£105,000	£0	

DFC Allocation & Adjustment

DFC allocation for 06/07

£46,585 £37,757 Plus/minus C/F £84,342

Amount available

-£20,658 (NB: To be drawn down from 07/08 Allocation) Under/over spend

School:

Skerne Park Primary

AMP Category

Work/Project

Justification

Budget

Mod - Primary DFC £0

Suitability

Funding required for additional costs

£130,000

Replacement School

incurred during construction phase

Totals £130,000

£30,000 £0

DFC Allocation & Adjustment DFC allocation for 06/07

£0 (NB. No DFC allocation for 3 years)

Plus/minus C/F

Amount available

£0

Under/over spend

£0

School:	Whinfield Primary					
AMP Category	Work/Project	Work/Project Justification	Budget		Primary	Fu
				DFC	Mod -	
Suitability	Remodeling works	Commitment towards 05-06 Remodeling works	£12,500	£12,500	£0	
Mechanical	Repairs to Hot Water	Essential repairs to renew defective	£30,000	£30,000	£0	
Suitability	System Temporary Classroom	heater and gas valve Annual commitment for hire of demountable accomodation	£22,500	£0	£22,500	
		Totals	£65,000	£42,500	£22,500	

DFC Allocation & Adjustment

DFC allocation for 06/07 £55,125
Plus/minus C/F £0
Amount available £55,125

Under/over spend £12,625 (NB. Carry forward to support anticipated 07/08 projects)

School:	Branksome Compreh	ensive				
AMP Category	Work/Project J	Justification	Budget		ary	Fı
Suitability Projects	extension to Design & Technology block and miscellaneous internal remodelling works	Required to redress deficiencies in teaching accommodation provision identified in the school Ofsted Report and subsequent feasibilty exercise. NB. Overall budget for works is £400k with work phased over two financial years, requiring further contribution of £60k (07/08	£215,023	₽ £60,000	🕾 Mod - Primary	£
External Walls Windows And Doors	Window Replacement - Phase 1	Modernisation - Comprehensives) and £125k (07/08 Pupil Places) Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and improve energy efficiency	000,002	£30,000	£0	
Mechanical Works	replacement works to heating, hot & cold	Preventative works to ensure that systems fully meet Legionella Health & Safety safety requirements	£85,000	£20,000		•
Electrical Works	water systems Replacement of aging control gear, electrical equipment and	Required to satisfy Health & Safety requirements and to ensure continuing operation of systems	000,083	£0	£0	
Urgent / Emergency Work	installations Replacement of worn ou workshop ventilation	t Required to satisfy Heath & Safety regulations and ensure that	£30,000	£0	£0	
Urgent / Emergency Work	equipment Miscellaneous fire stopping works to roofs	curriculum can continue to be taught Required to redress potential Health & Safety risk	£25,000	£0	£0	
External Areas	& ceiling voids Renew badly deteriorated playground	Require to redress potential Health & Safety risk	£21,100	£0	£0	

School:	Branksome Compre	hensive (Cont'd)				
AMP Category	Work/Project	Justification	Budget		Mod - Primary	Fu
Electrical Works	Replacement of obsolete telephone system	Replacement installation required to provide a new digital system that has capacity for 10 nr. mobile handsets, improves the available lines and features available to the school, and provide a better telecom service for	£17,000	£17,000	T- Mod -	
Roofing Works	Miscellaneous roofing works	parents, etc Provision for essential roofing repairs to prevent water ingress and resultant damage to structure, fixtures and	£10,850	£0	£0	£
Floors and Stairs	Renew badly deteriorated floor	finishes Require to redress potential Health & Safety risk Totals	£10,000 £583,973	£0	£0	£2

DFC Allocation & Adjustment

 DFC allocation for 06/07
 £90,840

 Plus/minus C/F
 £0

 Amount available
 £90,840

Under/over spend -£36,160 (NB. Draw down of 07/08 DFC required to enable main priority work to commence)

School:	Eastbourne Compre	hensive				
AMP Category	Work/Project	Justification	Budget		Mod - Primary	Fu
				DFC	- Wod	
Electrical Works	Replacement of aging control gear, electrical equipment and	Required to satisfy Health & Safety requirements and to ensure continuing operation of systems	£40,000	£40,000	£0	
External Walls Windows And Doors	installations Miscellaneous repairs/ replacement and redecoration	Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and improve energy efficiency	£25,000	£25,000	£0	
Urgent / Emergency Work	Miscellaneous fire stopping works to roofs	Required to redress potential Health	£25,000	£0	£0	£
	& ceiling voids	Totals	£90,000	£65,000	£0	£

DFC Allocation & Adjustment

DFC allocation for 06/07 £88,627 £0 Plus/minus C/F

£88,627 Amount available

£23,627 (NB. Carry forward to support anticipated 07/08 projects) Under/over spend

						•
AMP Category	Work/Project	Justification	Budget		rimary	Fu
				DFC	Mod - Primary	
Suitability Projects		Extensive refurbishment works are essential to redress major condition, suitability and sufficiency related needs. NB. The Authority has secured funding of £14.369m and the school is committed to contribute £172k from their DFC allocation, with the project phased over 3 financial years	£3,000,000	£0	£0	
External Walls Windows And Doors		Provision for essential repairs to satisfy Health & Safety requirements	£30,000	£10,000	£0	£
Mechanical Works		Provision for essential repairs to satisfy Health & Safety requirements	£30,000	£10,000	£0	£
External Areas	Renew badly deteriorated surface to	Require to redress potential Health & Safety risk	£24,000	£24,000	£0	
Electrical Works	Replacement of aging electrical equipment and installations	Provision for essential electrical repairs/renewal to satisfy Health & Safety requirements and ensure continuing operation of systems	£20,000	£0	£0	1
Int Walls & Doors	Replacement and upgrade of defective fire doors	Require to redress potential Health &	£20,000	£20,000	£0	
Redecoration		Required to improve general appearance of public areas	£13,000	£13,000	£0	
Roofing Works	Miscellaneous roofing works	Essential roofing repairs to prevent water ingress and resultant damage to structure, fixtures and finishes	£10,000	£10,000	£0	
Suitability Projects	Adaptation works to toilet compartment	Required to provide improved toileting & change facilities for a current pupil with an identified need.	£10,000	£0	£0	

School:	Hummersknott Co	Hummersknott Comprehensive (Cont'd)					
AMP Category	Work/Project	Justification	Budget		Primary	Fu	
External Areas	Repair defective/ spalling high level brickwork & copings	Provision for essential repairs to satisfy Health & Safety requirements	£10,000	£10,000	- poW £0	e	
		Totals	£3,167,000	£97,000	£0	£	

DFC Allocation & Adjustment

DFC allocation for 06/07

£132,656

Plus/minus C/F

£0

Amount available

£132,656

Under/over spend

£35,656 (NB. Carry forward to support anticipated 07/08 projects)

School:	Hurworth Compreh	ensive				
AMP Category	Work/Project	Justification	Budget		Mod - Primary	Fu
Mechanical Works	Miscellaneous repair/ replacement works	Provision for essential repair works to aging hot and cold water distribution systems to satisfy safety requirements and ensure continuing	£20,000	B DRC	- Wod £0	£2
Urgent / Emergency Work	Miscellaneous fire stopping works to roofs	operation of systems Required to redress potential Health & Safety risk	£25,000	£0	£0	£
External Areas	& ceiling voids Replace PE area that has badly deteriorated	Area virtually unusable, work required to redress impact upon delivery of the curriculum and	£45,000	£45,000	£0	
External Areas	Replace missing and defective fencing around tennis courts	Courts virtually unusable, work required to bring them back to required standard and to redress potential Health & Safety risk	£10,000	£10,000	£0	
		Totals	£100,000	£55,000	£0	£

DFC Allocation & Adjustment

£76,474 DFC allocation for 06/07 £0 Plus/minus C/F

£76,474 Amount available

£21,474 (NB. Carry forward to support anticipated 07/08 projects) Under/over spend

School:	Longfield Comprehe	ensive				
AMP Category	Work/Project	Justification	Budget		8 Mod - Primary	Fu
				DFC	Mod -	
Urgent / Emergency Work	Miscellaneous repair and replacement works to heating, hot & cold water systems	Preventative works to ensure that systems fully meet Legionella Health & Safety safety requirements	£150,000	£30,000	£0	£
Urgent / Emergency Work	Replacement of rotten and defective windows and doors - Phase 2	Badly deteriorating, required to prevent possible water ingress, address potential H&S risk and improve energy efficiency	£50,000	£0	£0	£
Roofing Works	Miscellaneous roofing works	Provision for essential roofing repairs to prevent water ingress and resultant damage to structure, fixtures and finishes	£50,000	£25,000	£0	
Electrical Works	Replacement of aging control gear, electrical equipment and	Required to satisfy Health & Safety requirements and to ensure continuing operation of systems	£25,000	£12,500	£0	£
Urgent / Emergency Work	installations Miscellaneous fire stopping works to roofs & ceiling voids	Required to redress potential Health & Safety risk	£25,000	£0	£0	£
External Areas	Construction of field drain	Essential drainage works to the playing field area to help minimise the potential for flooding of adjoining	£16,500	£0	£0	
Suitability Projects	Miscellaneous DDA related works	Provision for necessary adaptations to doorways and associated access routes	£15,000	£5,000	£0	
		Totals	£331,500	£72,500	£0	£

DFC Allocation & Adjustment

 DFC allocation for 06/07
 £101,179

 Plus/minus C/F
 £0

 Amount available
 £101,179

Under/over spend £28,679 (NB. Carry forward to support anticipated 07/08 projects)