

Appendix 4

SOUTH PARK INVENTORY

1. BUILDINGS AND STRUCTURES	CONDITION
Park Lodge (Park manager/Rangers/classroom/ bowling pavilion)	Refurbished
Café	Refurbished
Bandstand, Grade II listed	Restored
Terracotta fountain Grade II listed	Restored
Embankment Lodge	Repairs needed
Drinking fountain behind Embankment Lodge	Repairs needed
East Lodge (not part of MMP at present)	Repairs needed
Jardiniere	Minor repairs required
Fowler Memorial Plinth	Minor repairs required and new/replica sculpture on plinth
North and South Aviaries	Extensive council funded Improvement works to be carried out in early 2006
Fothergill Drinking Fountain	Restored
Parkside Road Bridge	Reinstated stone balusters with new lighting
2. FEATURE AREAS	
Rose garden	Restored
Sensory Garden (Grotto)	Restored
Rockery	Restored
Lake	Restored
3. BOUNDARIES	
Parkside and Grange Road: restored historic railings	Refurbished
Victoria Embankment entrance gates and piers	Refurbished
Main entrance gates (Parkside)	Restored/improved
North boundary to Henderson street: modern railings	Refurbished
South of Henderson Street: fences and hedges adjoin residential properties	
Around rose garden, west of river: red brick wall	Replaced with fencing
4. FURNITURE/EQUIPMENT	
Existing park benches refurbished steel	
Teesdale seat, by Lost-Art	New
Vesko PB 3001A seat with arms	New
Broxap Pierhead BX 2311 litter bin	New
Cycle stand, by Sheffield Broxap BX MW/SU/1	New
5. SPORT & RECREATION FACILITIES	
Showground (close mown amenity grass)	To be retained
Bowling greens (club facilities at Park Lodge)	To be retained
Play areas - under 5 and 5-12	New
Multi-court and skate park	New
Construction of sports changing pavilion in 2006 and improvement works to the five football pitches	Not yet in place
6. PATHS	
Path round showground	New path desirable
Low priority footpaths	Upgrading required
Historic Circuit Walk	Refurbished / extended
General path network	Sections require upgrading